

CASE STUDY:

Hyatt Regency Grand Cypress Hotel *Orlando, Florida*

The skylight sits above the main atrium and had significant leaking problems for many years. The skylight consisted of acrylic bubbles on a gutter system which was supported by a steel space frame. In heavy wind storms, some of the acrylic bubbles had even blown off the building. The owner wanted to replace the system with a hurricane compliant, energy efficient skylight that would not leak. Super Sky provided a custom glass skylight solution that solved all of the existing problems. This skylight removal and replacement was able to be accomplished with minimal disruption of the daily operation of the atrium space.



Before



After



Super Sky Products Enterprises, LLC

10301 N. Enterprise Drive, Mequon, WI 53092 • 800.558.0467 • 262.242.2000 • Fax: 262.242.7409

www.supersky.com